

### Spring feed right (standard)

Measuring Transducer T  
with device for fine adjustment

Spring holder  
T800/29000

O-ring-NBR

Measuring force (standard)  
spring 1.0N

Conversion to pneumatic feed right

Feed by spring

### Pneumatic feed right

Pneumatics switched off  
advance stroke by spring

Pneumatics switched on advance stroke  
to the right by compressed air

**Pneumatic cylinder T800/88000**

O-ring-NBR

Spring holder T800/29000

O-ring-NBR

Measuring force spring 1.0N

Conversion to pneumatic feed right

(For the left-hand pneumatic feed version, the assembly is reversed)



www.peterhirt.com

1002214

**Assembly drawing**

Pneumatic cylinder T800/88000

Masstab / Scale

1:1.5

mm

